Top 5 Deficiencies Reported (2019-2023)

Year	Deficiency	No. of Deficiencies	Deficiency %age
2023	Other (machinery) (13199)	469	3.51
	Other (fire safety) (07199)	402	3.01
	Lifeboats (11101)	292	2.19
	Auxiliary engine (13102)	252	1.89
	Ventilators, air pipes, casings (03108)	232	1.74
	Total Deficiencies : 13346		
2022	Other (fire safety) (07199)	328	3.31%
	Other (machinery) (13199)	265	2.67%
	Oil accumulation in engine room (07126)	207	2.09%
	Fire-dampers (07115)	194	1.96%
	Lifeboats (11101)	192	1.94%
	Total Deficiencies : 9908		
2021	Other (fire safety) (07199)	270	2.96%
	Other (machinery) (13199)	229	2.51%
	Lifeboats (11101)	202	2.21%
	Fire doors/openings in fire resisting divisions (07105)	173	1.89%
	Emergency, lighting, batteries and switches (04103)	173	1.89%
	Total Deficiencies : 9131		
2020	Other (fire safety) (07199)	285	3.07%
	Other (machinery) (13199)	235	2.53%
	Lifeboats (11101)	204	2.20%
	Other (Conditions of employment) (18299)	172	1.85%
	Lights, shapes, soud-signals (10109)	166	1.79%
	Total Deficiencies : 9288		
2019	Lifeboats (11101)	267	2.44%
	Other (fire safety) (07199)	264	2.41%
	Other (machinery) (13199)	240	2.19%
	Ventilators, air pipes, casings (03108)	209	1.91%
	Emergency, lighting, batteries and switches (04103)	197	1.8%
	Total Deficiencies : 10960		

Updated Date: 04 April 2024 IOMOU on Port State Control Next Update: April 2025